


IFC COLOMBO SRI LANKA

MONTHLY MARITIME SAFETY BULLETIN - JANUARY




COMPARISON OF INCIDENTS (2017 - 2021)




(Others include -Grounding, Collision, Fire On board and Other incidents)


Note: The patient reported on board SLFV 'DINAYA' (IMUL-A-1046 MTR) found dead subsequently



TYPE OF PLATFORMS



COST INCURRED BY SLN



TOTAL
26
INCIDENTS

26.92% ↑
COMPARED
WITH 2020

PATIENTS
1
ON BOARD

3.8%
of total incidents

TECHNICAL
9
FAILURE

34.6%
of total incidents

DETH OF
1
CREW MEMBER

3.8%
of total incidents

DISTRESS
5
BEACON ALERT

19.2%
of total incidents

MOB
2
VESSELS

7.7%
of total incidents

OTHER
4
INCIDENTS

15.4%
of total incidents

OVER DUE
4
VESSELS

15.4%
of total incidents

MRCC ACTIONS - JANUARY 2021



**ASSISTANCE
SECURED FROM SLN**

6



**COORDINATED
INCIDENTS**

15



**OWNER MADE OWN
ARRANGEMENTS AND
MONITORED**

5



BROADCAST- JANUARY 2021



Distress Broadcast on MOB of SLFV "SEEWISH 07"
(IMUL-A-0271-KLT) form 06 – 09 January 2021




Distress Broadcast on MOB of SLFV "THARUSHI 14"
(IMUL-A-1007-GLE) form 21 – 24 January 2021



Safety Broadcast on ran aground Merchant Vessel
"EUROSUN" (IMO: 9546227) from 23 – 29 January
2021



INCIDENT MAP OF JANUARY 2021



Technical Failure	Patient On board	Distress Beacon Alert	Grounded	Overdue	Fire On board	Death
Capsized	No Communication	Man Overboard Boat	Other			

Information Fusion Centre

Colombo, Sri Lanka

Tell - 0094 11 244 5368 | Fax - 0094 11 244 1454 | ifc@navv.lk

Copyright© 2020 IFC Colombo, Sri Lanka. All Rights Reserved